

The State of New Hampshire
Department of Environmental Services



Robert R. Scott, Commissioner

11/28/2022

SATISH PATEL 425 LAKE AVE INC 425 LAKE AVE MANCHESTER, NH 03103-

Subject Site: MANCHESTER, LAKE FOOD MART, 425 LAKE AVE NHDES Site # 200507041, UST Facility # 0115700

Reference: Underground Storage Tank Facility Inspection Report

On November 15, 2022 the New Hampshire Department of Environmental Services, Waste Management Division (NHDES) conducted an inspection of the underground storage tank (UST) system(s) at the subject site. The inspection was conducted to determine the level of compliance with key elements of the New Hampshire Code of Administrative Rules Env-Or 400 Underground Storage Facilities (UST Rules) and Env-Or 500, Recovery of Gasoline Vapors. These rules were established for the purpose of reducing the number of product releases to the environment from UST systems and to establish a leak detection system which would alert a facility owner or operator before significant environmental damage and economic loss occurs. The inspection conducted at this facility is part of the NHDES release prevention effort.

Deficiencies noted during this inspection warrant your facility to be considered in substantial non-compliance with applicable rules. This means they pose a threat of a release to the environment and may result in a release going undetected. The following deficiency(ies) requires your immediate attention:

TANK #1 (Containing REGULAR MASTER with Capacity of 15000 gallons)

Env-Or 406.13 requires the owner to conduct annual leak monitoring system testing for proper operation and submit test results to NHDES no later than 30 days after the date of the test. The NHDES inspector has determined the tank leak monitoring equipment was not tested annually for proper operation.

Please conduct annual leak monitor testing and submit passing test results to NHDES that meet the requirements of Env-Or 406.13(e) through (g).

If it is determined that the leak monitoring system is malfunctioning, Env-Or 406.02(c) requires the owner to repair the system and clear and reset any alarm condition to normal operating mode within 15 working days, or place the affected system(s) into temporary closure until satisfactory repairs are made.

Finally, if the leak monitor indicates a possible leak, the owner shall investigate the cause of the indication to determine if a leak has occurred, in accordance with Env-Or 406.04.

Env-Or 406.09 requires automatic line leak detectors to be tested annually in accordance with the manufacturer's requirements to confirm that they are operating in accordance with their designed functions and requires the facility owner to submit test results to NHDES no later than 30 days after the date of the test.

425 LAKE AVE INC DES Site # 200507041, UST Facility # 0115700 11/28/2022 Page 2 of 8

The NHDES inspector has determined the line leak detector was not tested annually for proper operation.

Please conduct annual line leak detection testing and submit passing test results to NHDES that meet the requirements of Env-Or 406.09(b) and (c).

If it is determined that the line leak detection system is malfunctioning, Env-Or 406.09(f) requires the owner to remove the affected piping system(s) from service until the line leak detector is repaired or replaced and passes the line leak detector test. Finally, if the line leak detection system indicates a possible leak, the owner shall investigate the cause of the indication to determine if a leak has occurred, in accordance with Env-Or 406.04.

Env-Or 406.13 requires the owner to conduct annual leak monitoring system testing for proper operation and submit test results to NHDES no later than 30 days after the date of the test. The NHDES inspector has determined the piping leak monitoring equipment was not tested annually for proper operation.

Please conduct annual leak monitor testing and submit passing test results to NHDES that meet the requirements of Env-Or 406.13(e) through (g).

If it is determined that the leak monitoring system is malfunctioning, Env-Or 406.02(c) requires the owner to repair the system and clear and reset any alarm condition to normal operating mode within 15 working days, or place the affected system(s) into temporary closure until satisfactory repairs are made.

Finally, if the leak monitor indicates a possible leak, the owner shall investigate the cause of the indication to determine if a leak has occurred, in accordance with Env-Or 406.04.

Env-Or 406.12(c) requires that no later than October 13, 2021 and triennially thereafter, all stage I system connection spill containment equipment that otherwise was not tested pursuant to Env-Or 406.12(a) shall be tested for tightness as specified in Env-Or 406.05 through Env-Or 406.08.

The NHDES inspector has determined the vapor spill containment integrity testing has not been conducted.

Please conduct triennial tightness testing of the spill containment, per Env-Or 406.12, and submit the passing test results to NHDES.

Please refer to Env-Or 406.08(i) for test failure requirements, Env-Or 408.03 for repair requirements, and Env-Or 406.12(g) for closure requirements, if applicable. For closure of a spill containment device, please submit a summary of closure activity per Env-Or 406.12(g) and Env-Or 408.03(e).

Env-Or 405.08 and Env-Or 406.02 require leak monitoring of tank systems to be installed and in good working order to continuously perform their original design function. Env-Or 406.02 requires the interstitial or annular space for tanks to be free of debris and water.

The NHDES inspector has determined the visual indicator power light for the tank leak monitoring system was not working or working properly.

Please repair or replace the visual indicator, verify the alarm is operational and submit maintenance documentation to NHDES.

425 LAKE AVE INC DES Site # 200507041, UST Facility # 0115700 11/28/2022 Page 3 of 8

TANK #2A (Containing REGULAR SLAVE with Capacity of 7500 gallons)

Env-Or 406.13 requires the owner to conduct annual leak monitoring system testing for proper operation and submit test results to NHDES no later than 30 days after the date of the test. The NHDES inspector has determined the tank leak monitoring equipment was not tested annually for proper operation.

Please conduct annual leak monitor testing and submit passing test results to NHDES that meet the requirements of Env-Or 406.13(e) through (g).

If it is determined that the leak monitoring system is malfunctioning, Env-Or 406.02(c) requires the owner to repair the system and clear and reset any alarm condition to normal operating mode within 15 working days, or place the affected system(s) into temporary closure until satisfactory repairs are made.

Finally, if the leak monitor indicates a possible leak, the owner shall investigate the cause of the indication to determine if a leak has occurred, in accordance with Env-Or 406.04.

Env-Or 406.13 requires the owner to conduct annual leak monitoring system testing for proper operation and submit test results to NHDES no later than 30 days after the date of the test. The NHDES inspector has determined the piping leak monitoring equipment was not tested annually for proper operation.

Please conduct annual leak monitor testing and submit passing test results to NHDES that meet the requirements of Env-Or 406.13(e) through (g).

If it is determined that the leak monitoring system is malfunctioning, Env-Or 406.02(c) requires the owner to repair the system and clear and reset any alarm condition to normal operating mode within 15 working days, or place the affected system(s) into temporary closure until satisfactory repairs are made.

Finally, if the leak monitor indicates a possible leak, the owner shall investigate the cause of the indication to determine if a leak has occurred, in accordance with Env-Or 406.04.

Env-Or 406.12(c) requires that no later than October 13, 2021 and triennially thereafter, all stage I system connection spill containment equipment that otherwise was not tested pursuant to Env-Or 406.12(a) shall be tested for tightness as specified in Env-Or 406.05 through Env-Or 406.08.

The NHDES inspector has determined the vapor spill containment integrity testing has not been conducted.

Please conduct triennial tightness testing of the spill containment, per Env-Or 406.12, and submit the passing test results to NHDES.

Please refer to Env-Or 406.08(i) for test failure requirements, Env-Or 408.03 for repair requirements, and Env-Or 406.12(g) for closure requirements, if applicable. For closure of a spill containment device, please submit a summary of closure activity per Env-Or 406.12(g) and Env-Or 408.03(e).

Env-Or 405.08 and Env-Or 406.02 require leak monitoring of tank systems to be installed and in good working order to continuously perform their original design function. Env-Or 406.02 requires the interstitial or annular space for tanks to be free of debris and water. The NHDES inspector has determined the visual indicator power light for the tank leak monitoring system was not working or working properly.

425 LAKE AVE INC DES Site # 200507041, UST Facility # 0115700 11/28/2022 Page 4 of 8

Please repair or replace the visual indicator, verify the alarm is operational and submit maintenance documentation to NHDES.

TANK #2B (Containing SUPER with Capacity of 7500 gallons)

Env-Or 406.13 requires the owner to conduct annual leak monitoring system testing for proper operation and submit test results to NHDES no later than 30 days after the date of the test. The NHDES inspector has determined the tank leak monitoring equipment was not tested annually for proper operation.

Please conduct annual leak monitor testing and submit passing test results to NHDES that meet the requirements of Env-Or 406.13(e) through (g).

If it is determined that the leak monitoring system is malfunctioning, Env-Or 406.02(c) requires the owner to repair the system and clear and reset any alarm condition to normal operating mode within 15 working days, or place the affected system(s) into temporary closure until satisfactory repairs are made.

Finally, if the leak monitor indicates a possible leak, the owner shall investigate the cause of the indication to determine if a leak has occurred, in accordance with Env-Or 406.04.

Env-Or 406.09 requires automatic line leak detectors to be tested annually in accordance with the manufacturer's requirements to confirm that they are operating in accordance with their designed functions and requires the facility owner to submit test results to NHDES no later than 30 days after the date of the test.

The NHDES inspector has determined the line leak detector was not tested annually for proper operation.

Please conduct annual line leak detection testing and submit passing test results to NHDES that meet the requirements of Env-Or 406.09(b) and (c).

If it is determined that the line leak detection system is malfunctioning, Env-Or 406.09(f) requires the owner to remove the affected piping system(s) from service until the line leak detector is repaired or replaced and passes the line leak detector test.

Finally, if the line leak detection system indicates a possible leak, the owner shall investigate the cause of the indication to determine if a leak has occurred, in accordance with Env-Or 406.04.

Env-Or 406.13 requires the owner to conduct annual leak monitoring system testing for proper operation and submit test results to NHDES no later than 30 days after the date of the test. The NHDES inspector has determined the piping leak monitoring equipment was not tested annually for proper operation.

Please conduct annual leak monitor testing and submit passing test results to NHDES that meet the requirements of Env-Or 406.13(e) through (g).

If it is determined that the leak monitoring system is malfunctioning, Env-Or 406.02(c) requires the owner to repair the system and clear and reset any alarm condition to normal operating mode within 15 working days, or place the affected system(s) into temporary closure until satisfactory repairs are made.

Finally, if the leak monitor indicates a possible leak, the owner shall investigate the cause of the indication to determine if a leak has occurred, in accordance with Env-Or 406.04.

425 LAKE AVE INC DES Site # 200507041, UST Facility # 0115700 11/28/2022 Page 5 of 8

Env-Or 406.12(c) requires that no later than October 13, 2021 and triennially thereafter, all stage I system connection spill containment equipment that otherwise was not tested pursuant to Env-Or 406.12(a) shall be tested for tightness as specified in Env-Or 406.05 through Env-Or 406.08.

The NHDES inspector has determined the vapor spill containment integrity testing has not been conducted.

Please conduct triennial tightness testing of the spill containment, per Env-Or 406.12, and submit the passing test results to NHDES.

Please refer to Env-Or 406.08(i) for test failure requirements, Env-Or 408.03 for repair requirements, and Env-Or 406.12(g) for closure requirements, if applicable. For closure of a spill containment device, please submit a summary of closure activity per Env-Or 406.12(g) and Env-Or 408.03(e).

Env-Or 405.08 and Env-Or 406.02 require leak monitoring of tank systems to be installed and in good working order to continuously perform their original design function. Env-Or 406.02 requires the interstitial or annular space for tanks to be free of debris and water. The NHDES inspector has determined the visual indicator power light for the tank leak monitoring system was not working or working properly.

Please repair or replace the visual indicator, verify the alarm is operational and submit maintenance documentation to NHDES.

DISPENSER #1/2

Env-Or 405.04 and Env-Or 406.01(a) require dispenser sumps to be installed that are liquidtight, free of liquid and debris, maintained and provided with continuous leak detection monitoring.

The NHDES inspector has determined the containment sump integrity testing for all dispenser pans has not been conducted.

Please conduct triennial tightness testing of the dispenser containment sump that meets the requirements of Env-Or 406.05 through Env-Or 406.08 or Env-Or 406.15. and submit the passing test results to NHDES.

Please refer to Env-Or 406.08 for test failure requirements, Env-Or 408.03 for repair requirements, Env-Or 406.14(h) and 408.06 through 408.10 for closure requirements, if applicable. Immediately conduct applicable notification and response actions required of Env-Or 600 if a release has occurred.

DISPENSER #3/4

Env-Or 405.04 and Env-Or 406.01(a) require dispenser sumps to be installed that are liquidtight, free of liquid and debris, maintained and provided with continuous leak detection monitoring.

The NHDES inspector has determined the containment sump integrity testing for all dispenser pans has not been conducted.

Please conduct triennial tightness testing of the dispenser containment sump that meets the requirements of Env-Or 406.05 through Env-Or 406.08 or Env-Or 406.15. and submit the passing test results to NHDES.

Please refer to Env-Or 406.08 for test failure requirements, Env-Or 408.03 for repair

425 LAKE AVE INC DES Site # 200507041, UST Facility # 0115700 11/28/2022 Page 6 of 8

requirements, Env-Or 406.14(h) and 408.06 through 408.10 for closure requirements, if applicable. Immediately conduct applicable notification and response actions required of Env-Or 600 if a release has occurred.

DISPENSER #5/6

Env-Or 405.04 and Env-Or 406.01(a) require dispenser sumps to be installed that are liquidtight, free of liquid and debris, maintained and provided with continuous leak detection monitoring.

The NHDES inspector has determined the containment sump integrity testing for all dispenser pans has not been conducted.

Please conduct triennial tightness testing of the dispenser containment sump that meets the requirements of Env-Or 406.05 through Env-Or 406.08 or Env-Or 406.15. and submit the passing test results to NHDES.

Please refer to Env-Or 406.08 for test failure requirements, Env-Or 408.03 for repair requirements, Env-Or 406.14(h) and 408.06 through 408.10 for closure requirements, if applicable. Immediately conduct applicable notification and response actions required of Env-Or 600 if a release has occurred.

DISPENSER #7/8

Env-Or 405.04 and Env-Or 406.01(a) require dispenser sumps to be installed that are liquidtight, free of liquid and debris, maintained and provided with continuous leak detection monitoring.

The NHDES inspector has determined the containment sump integrity testing for all dispenser pans has not been conducted.

Please conduct triennial tightness testing of the dispenser containment sump that meets the requirements of Env-Or 406.05 through Env-Or 406.08 or Env-Or 406.15. and submit the passing test results to NHDES.

Please refer to Env-Or 406.08 for test failure requirements, Env-Or 408.03 for repair requirements, Env-Or 406.14(h) and 408.06 through 408.10 for closure requirements, if applicable. Immediately conduct applicable notification and response actions required of Env-Or 600 if a release has occurred.

The above noted **deficiencies must be corrected within 30 days** of the date of this inspection. To verify that the proper corrective measures were taken, documentation, in the form of a report from the certified technician that effected the repair, testing results, invoices, inventory records, photographs, etc., indicating the date and description of the corrective measures taken must be **submitted to NHDES within 45 days** of the date of this inspection. Please be advised that failure to correct the deficiencies in a proper and timely manner will result in NHDES proceeding under the NHDES Compliance Assurance Response Policy to determine an appropriate enforcement response. Please note that New Hampshire RSA 125-C and 146-C authorize permit revocation, administrative fines not to exceed \$2,000 per violation, administrative orders, delivery prohibition, injunctive relief, and civil penalties not to exceed \$10,000 per violation per day of continuing violation, and \$25,000 for each continued day of a repeat violation.

425 LAKE AVE INC DES Site # 200507041, UST Facility # 0115700 11/28/2022 Page 7 of 8

Your signature below acknowledges that you were briefed by NHDES staff concerning the noted deficiencies. Should you have any questions concerning the content of this letter, please contact me in the Waste Management Division of NHDES at (603) 271-3899. NHDES appreciates your willingness to comply with the UST program in an effort to preserve New Hampshire's environment.

Sincerely,

etzell

HARDING SCHOFIELD, Inspector

11/28/2022

Date

SATISH PATEL, Facility Manager

Date

Important Dates

Requirement	Tanks	Next Date Due	Frequency
Tank Leak Monitor Test	1, 2A, 2B	Past Due	Annual
LLD Function Check	1, 2B	Past Due	Annual
Tank Corrosion Protection Test	N/A	N/A	Every 3 years
Piping Corrosion Protection Test	N/A	N/A	Every 3 years
Fittings Corrosion Protection Test	N/A	N/A	Every 3 years
Spill Bucket Tightness Testing	1, 2A, 2B	12/15/2023	Every 3 years OR monthly interstice monitoring
Overfill Testing	1	9/28/2024	Every 3 years
Overfill Testing	2A, 2B	12/15/2023	Every 3 years
Primary Containment System Tightness Test	1, 2A, 2B	12/23/2023	Every 3 years
Operator Monthly Checklist			Monthly

425 LAKE AVE INC DES Site # 200507041, UST Facility # 0115700 11/28/2022 Page 8 of 8

GEORGE GEKIS - B	11/18/2023	Every 2 years
Operator Training		
GEORGE GEKIS - A	11/18/2023	Every 2 years
Operator Training		
SATISH K. PATEL - A	10/7/2023	Every 2 years
Operator Training		