

## Stockman, Robert

---

**From:** Stockman, Robert  
**Sent:** Monday, November 27, 2023 1:36 PM  
**To:** Jones, Matthew  
**Subject:** FW: Somersworth one stop II UST# 0111910

Matt received this from Bryans ( Nexttest) integrity test. The primary coating has a slit in it but no leak. It's on the super primary line which is empty. Another one that had the testing boot covering it. Fortunately, the line and tank are empty from red tag. All four sumps failed the test which I knew they would. Mike Lowry is aware that he needs to fix and replace piping. Everything is logged in.

---

**From:** Stockman, Robert <[robert.stockman@des.nh.gov](mailto:robert.stockman@des.nh.gov)>  
**Sent:** Monday, November 27, 2023 1:18 PM  
**To:** Stockman, Robert <[ROBERT.L.STOCKMAN@des.nh.gov](mailto:ROBERT.L.STOCKMAN@des.nh.gov)>  
**Subject:** FW: Somersworth one stop II

---

**From:** Rob Stockman <[rstockman@metrocast.net](mailto:rstockman@metrocast.net)>  
**Sent:** Wednesday, November 22, 2023 8:21 AM  
**To:** Stockman, Robert <[robert.stockman@des.nh.gov](mailto:robert.stockman@des.nh.gov)>  
**Subject:** Somersworth one stop II

---



super primary line inside the STP sump.





primary has a slit down the middle on the top part of the primary line inside dispenser.





Sent from my iPhone