

The State of New Hampshire

DEPARTMENT OF ENVIRONMENTAL SERVICES



Thomas S. Burack, Commissioner

9/26/2016

TANVEER CHAUDHRY TANVEER CHAUDHRY 297 UNION AVE LACONIA, NH 03246-

Subject Site: LACONIA, SHOP EXPRESS LACONIA, 297 UNION AVE

DES Site # 199801035, UST Facility # 0111173

Reference: Underground Storage Tank Facility Inspection Report

On September 26, 2016 the New Hampshire Department of Environmental Services, Waste Management Division (DES) conducted an inspection of the underground storage tank (UST) system(s) at the subject site. The inspection was conducted to determine the level of compliance with key elements of the New Hampshire Code of Administrative Rules Env-Or 400 Underground Storage Facilities (UST Rules) and Env-Or 500, Recovery of Gasoline Vapors. These rules were established for the purpose of reducing the number of product releases to the environment from UST systems and to establish a leak detection system which would alert a facility owner or operator before significant environmental damage and economic loss occurs. The inspection conducted at this facility is part of the DES release prevention effort.

The DES is happy to report there were no deficiencies found during this inspection.

Should you have any questions concerning the content of this letter, please contact me in the Waste Management Division of DES at (603) 271-3899. DES appreciates your willingness to comply with the UST program in an effort to preserve New Hampshire's environment.

Sincerely,

The the	9/26/2016	
ROBERT STOCKMAN, Inspector	Date	
TANVEER CHAUDHRY, Facility Manager	Date	

Telephone: (603) 271-3899 Fax: (603) 271-2181 TDD Access: Relay NH 1-800-735-2964

Important Dates

Requirement	Tanks	Next Date Due	Frequency
Tank Leak Monitor Test	5, 6	3/18/2017	Annual
LLD Function Check	5, 6	3/18/2017	Annual
Tank Corrosion Protection Test	N/A	N/A	Every 3 years
Piping Corrosion Protection Test	N/A	N/A	Every 3 years
Fittings Corrosion Protection Test	N/A	N/A	Every 3 years
Spill Bucket Tightness Testing	5, 6	12/22/2017	Every 3 years
Overfill Testing	5, 6	9/26/2019	Every 3 years
Sump Tightness Testing	5, 6	12/22/2017	Every 3 years
Primary Containment System Tightness Test	5, 6	12/22/2017	Every 3 years
Operator Monthly Checklist			Monthly