

ANNUAL LINE LEAK DETECTOR TEST FORM FOR AST AND UST SYSTEMS OIL REMEDIATION AND COMPLIANCE BUREAU



AST: RSA 146-A, Env-Or 306.12; UST: RSA 146-C, Env-Or 406.07, 406.09

THE OWNER SHALL SUBMIT A COPY OF THE ANNUAL TEST REPORT TO NHDES *WITHIN 30 DAYS* AFTER TESTING. Keep a completed copy of this for owner/operator records.

		<u></u>			
NHDES Site # 200507041			cility ID # 0115700		
Facility Name: LAKE FOODMACT	Towr	r/City: MAN	HESTER		
Physical Address of Facility: 435 L	AKE ALE				
1B. Owner Information					
그러지 내 [1811] 그는 학생 기고 가장 학생들이 되는 것이 되었다. 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그		16. Harris 1. Ha			
Name: Sotish Patel Mailing Address: 425 Lake	4	1 - 40//	03/01		
Daytima Phana: 679 720 64	Ave, Man	1chest NH	<u>03707</u>	(3)	
Mailing Address: 425 Lake AVE, Manchest NH 03/01 Daytime Phone: 978-729-8212 Email: Satish 0057 @gmail. Com.					
2. As required by rules, all pressurize restrict or stop the flow of the store 10 pounds per square inch line pr they are operating according to re	ed substance upo essure. Automati	n detecting a lea c line leak detec	k at a rate of 3 ga	allons per hour at	t a pressure of
3. Line leak detector is required to be Test Date: 12/2/22	tested in-place. D -	o not remove an	d test outside the	e system.	
Testing Information and Results:	AST 🗌	ust 💢			
4-2-47	4	Tank # AA	Tank # ΩB		
Tank # (for split tanks use 1(a), 1(b))	Tank # 1_	Tank # 'Q/\	Iank # AD	Tank #	Tank #
Test Location:	Tank #	Tank # Q/	Iank # AD	Tank #	Tank #
	REGULAR	REGULAR SLAVE	Super	Tank #	Tank #
Test Location:				Tank #	Tank #
Test Location: Product Stored: (gas, diesel, etc.)	REGULAR	REGIULIAE SLIAVE	Super	Tank #	Tank #
Test Location: Product Stored: (gas, diesel, etc.) Capacity: (gallons)	REGULAR 15,000	REGIULAE SLAVE 71500	SUPER 71500	Tank #	Tank #
Test Location: Product Stored: (gas, diesel, etc.) Capacity: (gallons) LLD Manufacturer:	REGULAR 15,000 VEEDER - ROOT	REGULAR SLAVE 71500 STPHON	SUPER 71500 VEEDER-ROOT	Tank #	Tank #
Test Location: Product Stored: (gas, diesel, etc.) Capacity: (gallons) LLD Manufacturer: LLD Model Number:	REGULAR 15,000 VEEDER - ROOT 859080-001	REGULAR SLAVE 71500 STPHON	SUPER 71500 VEEDER-ROOT 859080-001		Tank #
Test Location: Product Stored: (gas, diesel, etc.) Capacity: (gallons) LLD Manufacturer: LLD Model Number: Tested Leak Rate: (gallons per hour)	REGULAR 15,000 VEEDER - ROOT 859080-001 310 XI Pass Fail	REGULAR SLAVE 71500 STPHON STPHON Pass Fail	SUPER 715 00 VEEDER-ROOT 859080-00 3:0 Pass Fail		
Test Location: Product Stored: (gas, diesel, etc.) Capacity: (gallons) LLD Manufacturer: LLD Model Number: Tested Leak Rate: (gallons per hour) Results:	REGULAR 15,000 VEEDER - ROOT 859080-001 310 XI Pass Fail	REGULAR SLAVE 71500 STPHON STPHON Pass Fail	SUPER 715 00 VEEDER-ROOT 859080-00 3:0 Pass Fail		
Test Location: Product Stored: (gas, diesel, etc.) Capacity: (gallons) LLD Manufacturer: LLD Model Number: Tested Leak Rate: (gallons per hour) Results: Complete the following only if any of the ab	REGULAR 15,000 VEEDER - ROOT 859080-001 310 XI Pass Fail	REGULAR SLAVE 71500 STPHON STPHON Pass Fail	SUPER 715 00 VEEDER-ROOT 859080-00 3:0 Pass Fail		
Test Location: Product Stored: (gas, diesel, etc.) Capacity: (gallons) LLD Manufacturer: LLD Model Number: Tested Leak Rate: (gallons per hour) Results: Complete the following only if any of the ab	REGULAR 15,000 VEEDER - ROOT 859080-001 310 XI Pass Fail	REGULAR SLAVE 71500 STPHON STPHON Pass Fail	SUPER 715 00 VEEDER-ROOT 859080-00 3:0 Pass Fail		

An automatic line leak detector failure shall be indicated by a leak rate of greater than 3 gallons per hour at a pressure of 10 pounds per square inch line pressure within one hour. The failed line leak detector shall be repaired or replaced immediately. The affected piping system(s) shall be taken out of service until satisfactory repairs are made or the line leak detector is replaced.

ORCB.WMD@des.nh.gov

Fax: (603) 271-2181

TDD Access: Relay NH (800) 735-2964